

GOUGH 86

ONDERWERP • SUBJECT

NEW BRIDGE

COPY OF "PHOTO" REPORT.



NEW TIN CRUSHER ENCLOSURE:
IT IS RECOMMENDED THAT THE
FRONT BLOCKBOARD PANELS
BE REPLACED WITH "LINDE
PANELS OR ALUMINIUM
SHEETING.



NEW BRIDGE JUST COMPLETED.
NARROW GAUGE STEEL CATWALKS
WILL BE AN IMPROVEMENT.



NAME PLATE: BRIDGE
NAMED AFTER THE
BLECHNUM FERN COMMON
TO THIS ISLAND.



CONDITION OF OLD
BRIDGE



NEW FILTERS INSTALLED
TO IMPROVE WATER
PRESSURE ON HOT
WATER CYLINDERS.



THE FIVE RESERVE
WATER TANKS WHICH
NEED A NEW STAND,
TANKS SHOULD ALSO
BE REPLACED.



CRANE POWER SHACK:
FRONT DOOR WAS BLOWN
OFF AND A NEW STEEL
DOOR IS RECOMMENDED
FOR 1987. TEMPORARY
REPAIR WAS EFFECTED
BUT FRAME IS DAMAGED.



CRANE POWER SHACK:
SIDE DOORS WERE
COMPLETELY BLOWN OFF
AND HAS SINCE BEEN
REPLACED WITH A PURPOSE
MADE GALV. STEEL UNIT.



LANDING STAGE HAS BEEN
ENLARGED FROM CRANE
EDGE TILL POWER SHACK.
SERVICE WAS STILL INCOMPLETE
AT TIME OF "PHOTO"